

08/942005





FIG. 2






FIG. 3

08/942005




FIG. 4A

68/942085

ALERT/TYPE	Displayed Description
CPU	CPU identified by the CPU Number failed because of high temperature and/or low power
SYSTEM BOARD FAN	The speed of the system board fan identified by the Cooling Fan Number has dropped below the minimum limit.
TEMPERATURE SENSOR	The temperature of the system board fan identified by the temperature sensor number has dropped below the minimum limit.
POWER SUPPLY	Power Supply identified by the Power Supply Number has been extracted or inserted or has gone into an abnormal state, please look into the Help file for more detail
ADAPTER	The adapter identified by the Adapter Number or its driver is malfunctioning.
CANISTER	The Canister identified by the Canister Number has either been extracted or inserted.
SLOT FAN	The speed of the I/O slot fan identified by the Slot Fan Number has dropped below the minimum limit (slotFanMinSpeed).
CANISTER FAN	The speed of a fan in the canister identified by the Canister Number has dropped below the minimum limit.

FIGURE 4B

08/94/2003

ALERT/TYPE	Displayed Description
CPU	CPU identified by the CPU Number failed because of high temperature and/or low power
SYSTEM BOARD FAN	The speed of the system board fan identified by the Cooling Fan Number has dropped below the minimum limit.
TEMPERATURE SENSOR	The temperature of the system board fan identified by the temperature sensor number has dropped below the minimum limit.
POWER SUPPLY	Power Supply identified by the Power Supply Number has been extracted or inserted or has gone into an abnormal state, please look into the Help file for more detail
ADAPTER	The adapter identified by the Adapter Number or its driver is malfunctioning.
CANISTER	The Canister identified by the Canister Number has either been extracted or inserted.
SLOT FAN	The speed of the I/O slot fan identified by the Slot Fan Number has dropped below the minimum limit (slotFanMinSpeed).
CANISTER FAN	The speed of a fan in the canister identified by the Canister Number has dropped below the minimum limit.

FIGURE 4B

88/942005




FIG. 5

08/94/2005

Maestrio Central - [Log Window]

The diagram shows a central 'Log Window' window with various components labeled around it: 602, 604, 606, 608, 600, 612, 614, and 616. The components are connected to the log window, suggesting they are part of a system that generates logs.

Sequence	Date/Time	Source	Category	Description	Action
baba 1	11:29:16 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 2	11:29:17 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 3	11:34:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 4	11:34:39 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 5	11:36:36 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 6	11:36:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 7	2:04:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 8	2:05:14 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 9	2:05:17 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 10	2:05:18 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 11	2:06:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 12	2:07:35 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 13	2:07:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 14	2:07:37 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 15	2:08:49 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 16	2:09:28 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 17	3:01:10 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 18	3:01:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba 19	6:36:25 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 20	6:36:35 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 21	6:44:04 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 22	6:44:06 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 23	6:44:55 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 24	6:44:57 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba 25	6:48:42 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...

NetBios server discovered on network domain

FIG. 5

08/94 2005




FIG. 7

08/4/2005




FIG. 8

08/942005




FIG. 9